



CDOT Rapid Response to Hydrogen Cracking in Grade 100 Steel Welds at Blue Mesa Reservoir Bridges

Natasha Butler, PE

Colorado Department of Transportation

Keely Matson, PE

Michael Baker International



Francisco J. Bonachera M., PhD, PE, Purdue University



CDOT Overview




CDOT Overview




Project Location

- Blue Mesa Reservoir
- 3.5-4 hours from Colorado Springs or Denver
- Located in a very remote part of the mountains



Blue Mesa CM/GC Overview

- CDOT holds contracts with the Designer, CM, and ICE (Independent Cost Estimator)
- Blue Mesa Benefits
 - Material availability and pricing
 - Risk identification
 - Schedule
 - Constructability feedback
 - Resource allocations
 - Plans and specifications quality review
 - Phasing and construction access worked into design



Blue Mesa Bridges - General Information

- Both bridges built 1963, FAIR condition
- K-07-A
 - US 50 over the Lake Fork at mile marker 132.69
 - Six span, continuous composite welded girder bridge. 993ft, 300ft max span
 - Spans 3, 4, and 5 are Non-Redundant Steel Tension Members (NSTM).
- K-07-B
 - US 50 over the Blue Mesa Reservoir at mile marker 136.16
 - 10 span, continuous composite welded girder bridge. 1,532ft, max span 360ft
 - Spans 5, 6, and 7 are NSTM.
- 1 lane each direction

K-07-A



K-07-B


Blue Mesa Project

- On December 31, 2021, FHWA issued a memo requiring the identification, testing, and repair of T1 steel bridges with NSTM (Non-redundant Steel Tension Members)
- Colorado identified two Blue Mesa bridges as having main spans are composed of 100 ksi T1 Steel built-Up (welded) NSTM members



What Is T1 Steel?

- High strength steel developed in the 1950's and used 1950s - 1980s
- ASTM A514 or A517 designation
- $F_y = 100 \text{ ksi}$: $F_u = 110 \text{ ksi}$
- T-1 is US Steel marketing name
- Weldability issues



Low Carbon Tempered Martensite

[Proven Engineering Material: T1 Steel \(youtube.com\)](https://www.youtube.com/watch?v=...)

Timeline

Inspection and Design

April 8 - Start of visual inspection

April 11 - Visual finding of first crack

April 18 - Visual finding of second crack

April 18 - Bridge closed to traffic

April 20 - Benesch, BDI, Michael Baker & Kiewit retained

April 22 - Begin NDE inspection & design

April

K-07-B Inspection and Design

May 24 - UT Butt weld inspection completed

May 25 - K-07-B MT fillet weld testing

May 31 - Critical repair plans issued

May

Inspection and Design

K-07-B MT fillet weld testing

June

Construction

June 5 - Shop drawings & fab start

June 11 - Begin critical repairs

K-07-A Inspection and Design

July 8-Aug 3 - K-07-A MT fillet weld testing

Aug 1 - K-07-B permanent repairs plans issued

Aug 11 - K-07-A permanent repairs plans issued

July-December

July 2 - Critical repair complete

July 3 - K-07-B open to limited traffic

July 6 - K-07-B begin permanent repairs

August 12 - K-07-A begin permanent repairs

November 12 - Last bolt installed

Timeline

Inspection and Design

April 8 - Start of visual inspection

April 11 - Visual finding of first crack

April 18 - Visual finding of second crack

April 18 - Bridge closed to traffic

April 20 - Benesch, BDI, Michael Baker & Kiewit retained

April 22 - Begin NDE inspection & design



April

May

Timeline

K-07-B Testing and Design

May 24 - UT Butt weld inspection completed

May 25 - K-07-B MT fillet weld testing


May 31 - Critical repair plans issued

Site Constraints

- Weight restrictions
- Access
- Paint
- Wind
- Remote location

May

June



K-07-B Testing and Design

Design and Construction

Timeline

Inspection and Design


On-going K-07-B MT fillet weld testing

Construction

June 5 - Shop drawings & fab start

June 11 - Begin critical repairs

June



Design and Construction

K-07-A Inspection and Design

Timeline

K-07-A Inspection and Design

July 8-Aug 3 - K-07-A MT Fillet weld testing

Aug 1 - K-07-B Permanent repairs plans issued

Aug 11 - K-07-A Permanent repairs plans issued

Construction


July 2 - Critical repair complete

July 3 - K-07-B open to limited traffic

July 6 - K-07-B Begin Permanent Repairs

August 12 - K-07-A Begin Permanent Repairs

November 12 – Last Bolt Installed




July-December

K-07-A Inspection and Design

Bridge B - T1 Butt Weld Defects Map


UT RESULTS ARE PRELIMINARY




UT RESULTS ARE PRELIMINARY

- Class A indications
- Class B and C Indications
- Class D indications and None

Bridge B - T1 Butt Weld Defects Map



Bridge B Critical Repairs - Designed for Speed





Bridge B – Critical Repairs

- Open for July 4th
- Address flange to flange surface indications
- Use material that is immediately available
- Detail considering the loading limitations



Web-Flange Fillet Weld Cracking




Bridge B Permanent Repair Options Drivers

- Prevalence of fillet weld cracks
- Availability 100 ksi material
- Substructure capacity
- Schedule risk
- Historic bridge





Permanent Repair Schematic




Top Flange Repairs

- Local splice
- Minimize deck removal
- Minimize duration
- Grade 50 for speed



Connection to Initial Repairs




Collaboration with S-BRITE Center

- Steel Bridge Research, Inspection, Training and Engineering (S-BRITE) Center
 - Led by Dr. Robert Connor at Purdue University
- Provides expertise and resources to partners: 24 states and FHWA
 - Training, courses, research, inspection, expertise network (DEN), etc.
- Currently developing a bridge engineering program within the Lyles School of Civil and Construction Engineering
- Plans for a bridge engineering education center



Innovative Crack Arrest Strategy

- T1 steel with weld embrittlement issues
- Widespread defect indications in web-to-flange welds
- The extent of the indications made traditional repairs (grinding/coring) infeasible
- Nonredundant Steel Tension Member (NSTM, old FCM)
- The high number of defects also raised the likelihood of undetected cracks
- These conditions required a continuous retrofit, effective regardless of crack location, rather than localized repairs at each indication




Typical Approaches and Limitations

- Common retrofit methods: coring and dogbone details
 - Dogbones were impractical due to extensive overlap and risk of flange-web separation
- Web-splicing (plates on both sides + angle connections) was unsuitable because:
 - Excessive added weight,
 - Fabrication and fit-up with other repairs
- Widespread cracking meant localized strategies would be ineffective
- Inspection uncertainty required a location-independent crack-arrest mechanism




Preliminary Retrofit Development

- Retrofit concept based on understanding stress-field changes caused by bolt holes and how cracks respond to them
- Cracks tend to grow toward bolt holes due to stress concentrations and away from stress-vacuum regions
- Hole size chosen to match bolts used in other repairs
- Spacing (gage/pitch) evaluated using the infinite-plate stress model, ensuring cracks redirect toward the holes when tensile stress normal to propagation \geq applied stress
- Focused on the region between bolts closest to the tension flange, where cracks would “avoid” the first bolt row
- A third row was added for redundancy
- Multiple spacing patterns were developed and then prepared for analytical validation



Retrofit Validation

- Validation performed at Purdue University by Dr. Korkmaz and Dr. Connor using Abaqus FEA
- Crack behavior modeled using Extended Finite Element Method (XFEM)
- XFEM employs enrichment functions enabling:
 - Heaviside discontinuity modeling,
 - Accurate crack-tip stress fields through stress-intensity functions
- XFEM's key benefit: no remeshing required as cracks grow
- Bolt-pattern performance tested using cracks initiated at various distances and directions from bolt holes
- Multiple crack-propagation criteria evaluated (energy-release rate, mode mixity, etc.)
- All simulations showed cracks arresting in the first or second bolt row, with no propagation beyond row two



Fit-up Modifications

- Final retrofit: three bolt rows with defined minimum and maximum spacing limits
- Web reinforcement plates placed on both sides to maintain capacity if cracks arrested at bolt holes
- Retrofit required compatibility with other repairs, including:
 - Cored web-crack locations,
 - Existing flange splice retrofits
- Where bolt spacing conflicted with prior repairs, dogbone crack-arrest details were used instead of altering spacing
- These adjustments preserved consistent crack-arrest performance across the structure



Fun Facts

Repairs at a glimpse

- **118 splices tested**
- **289 indications found**
- **35,207 SF of primer**
- **410 tons of additional steel**
- **51,504 bolts (57 tons)**

Acknowledgements

- CDOT Region 3 and Staff Bridge
- Kiewit
- Michael Baker International
- Benesch
- Bridge Diagnostics, Inc.
- Dr. Robert Connor
- Dr. Cem Korkmaz
- S-BRITE Center at Purdue University
- FHWA
- Coating Specialists
- eO
- ICE
- KTA
- Stantec
- Ulteig
- W&W AFCO
- Gunnison County
- Brand Safway
- CIG
- Rocksol



Lessons Learned

- Collaboration - *Everyone has a common goal*
- Girder bridges offered some very unique challenges
- Bridge A – Forgo Testing and went straight to repair/reinforcement.
- Communication
 - Internal and externally
 - Many moving pieces and parts
- CM/GC benefits
 - Improved constructability
 - Material procurement / schedule



Thank You

